

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                       |                           |                           |                        |
|-----------------------|---------------------------|---------------------------|------------------------|
| Intersection ID: 6039 | Main Street: DELLINGER_DR | Cross Street: MILHAVEN_LN | Location: SW           |
| ADA ID: 0D98CE564D6B  | Ramp Type: Directional1   | Initial Pass/Fail: Fail   | Overall Compliance: No |
|                       |                           | Severity Score: 25        |                        |

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Entire Ramp.**

Surveyor Notes:

**VEGETATION OVERGROWTH**

PROW/ADA:

**R304.5.3**

| Compliance | Description           | Data | Compliance | Description                 | Data |
|------------|-----------------------|------|------------|-----------------------------|------|
| N/A        | Ramp Length (in)      | 20.5 | N/A        | Grade Break?                | N/A  |
| Yes        | Ramp Width (in)       | 65.0 | N/A        | Grade Break Slope (%)       | 0.0  |
| Yes        | Ramp Slope (%)        | 6.9  | N/A        | Grade Break XSlope (%)      | 0.0  |
| No         | Ramp XSlope (%)       | 7.5  |            |                             |      |
| N/A        | Flare Type LT         | N/A  | N/A        | Flare Type RT               | N/A  |
| N/A        | Flare Slope LT (%)    | N/A  | N/A        | Flare Slope RT (%)          | 0.0  |
| N/A        | Flare Traversable LT? | N/A  | N/A        | Flare Traversable RT?       | N/A  |
| N/A        | Landing Length (in)   | 0.0  | N/A        | DWS Provided?               | N/A  |
| N/A        | Landing Width (in)    | 0.0  | N/A        | DWS Contrast?               | N/A  |
| N/A        | Landing Slope (%)     | 0.0  | N/A        | DWS Length (in)             | N/A  |
| N/A        | Landing X Slope (%)   | 0.0  | N/A        | DWS Full Width?             | N/A  |
| N/A        | Landing Curb? (Y/N)   | N/A  | N/A        | DWS Offset LT (in)          | N/A  |
| N/A        | Shared Landing?       | N/A  | N/A        | DWS Offset RT (in)          | N/A  |
| N/A        | Gutter Ponding?       | 0.0  | N/A        | Gutter Slope (%)            | N/A  |
| N/A        | Gutter Lip Ht (in)    | 0.0  | N/A        | Gutter X Slope (%)          | N/A  |
| N/A        | Painted X Walk1?      | No   |            | Road Slope (%)              | 0.6  |
|            | X Walk 1 Direction    | To N |            | Road X Slope (%)            | 1.0  |
|            | X Walk 1 Width (in)   | N/A  |            | Clear Space?                | N/A  |
|            | X Walk 1 Slope (%)    | 0.6  | N/A        | Clear Space to XWalk (in)   | N/A  |
|            | X Walk 1 X Slope (%)  | 1.0  | N/A        | Storm Grate/Utility Hazard? | N/A  |
| N/A        | Ramp inside XWalk1?   | N/A  |            | Storm Grate/Utility Type    |      |
| N/A        | Any Obstructions?     | N/A  |            |                             | N/A  |
|            | Obstruction Type      |      | Yes        | Surface Condition? (G/P)    | Good |
|            |                       |      | N/A        | Curb Slope (%)              | N/A  |

Total Cost: \$ 1600.00

|                         |              |
|-------------------------|--------------|
| Street 1 Name           | DELLINGER DR |
| Stop Condition-Street 1 | StopSign     |
| Street 2 Name           | N/A          |
| Stop Condition-Street 2 | N/A          |

