cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 48193	193 Main Street: BLAKENEY_CENTRE_DR			Cross Street: BLAKENEY_PROFESSIONAL_DR				Location:	SE
ADA ID: 0D99A981CD82 Ramp Type: PerpDiag			Initial	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp	o With	N/A	Ramp Length (in)	50.0	No	Ramp Slope (%)	8.6
		Two New Directional Ramps or Equivalent.	r	Yes	Ramp Width (in)	50.0	No	Ramp XSlope (%)	5.3
BLAVE				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
CEL XEMENC				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
- Ale				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	AL DO			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
and the second sec	00	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	5 Martin	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	BITTO States			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
PROW/ADA: Not Found, R304.2.2, R304.5.3				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	Yes
					X Walk 1 Direction	To N		X Walk 2 Direction	To NW
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	56.0
Street 1 Name BLAKENEY PROFESSIONAL DR					X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	3.8
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	2.3
Street 2 Name	BLAKENEY CENTRE DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 1	StopSign				Road Slope (%)	4.3	N/A	Clear Space?	N/A
					Road X Slope (%)	2.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

