cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 52100	Main Street: FRED_D_ALEXANDER_BV			Cross Street: LITTLE ROCK RD					NW
							Location:		
ADA ID: 0DF912991DA5 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No						33.75
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
12. 1 1 2. 2	The second	Possible Solutions:	Compliance Description			Data	Comp	liance Description	Data
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Second & Carton	Remove & Replace Entire Ramp.	Ν	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	14.5
to participant	and the second s		Ν	lo	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	1.8
	A A		Ν	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	5. 5. A		Ν	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	a sta		N	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A A	BA AND		Ν	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:	N	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
<u>لم</u>	The second secon	N/A	N	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
* 19 201			Ν	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A A A A A A A A A A A A A A A A A A A	ار کار کار کار کار کار کار کار کار کار ک		N	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Star 1	Car and		N	N/A	Shared Landing?	N/A			
	No.	PROW/ADA:	N	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
NUTURA A	the second secon	R304.5.1, R304.2.2	Ν	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	the		Ν	N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
1 Malen	A LANDAN				X Walk 1 Direction	To S		X Walk 2 Direction	N/A
AN A MARCANA CONTRACTOR			Ν	N/A	X Walk 1 Width (in)	110.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	LITTLE ROCK RD				X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		Ν	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			١	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A



Good

