


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 26384	Main Street: BEVINGTON_PL	Cross Street: ELM_LN	Location: SE
ADA ID: 0E039DBC995	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 37.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance													
	Possible Solutions:		Compliance			Description			Data	Compliance			Description			Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)			60.0			No	Ramp Slope (%)			12.1		
			Yes	Ramp Width (in)			57.0			No	Ramp XSlope (%)			6.2		
			N/A	Flare Type LT			N/A			N/A	Flare Type RT			N/A		
			N/A	Flare Slope LT (%)			N/A			N/A	Flare Slope RT (%)			N/A		
			N/A	Flare Traversable LT?			N/A			N/A	Flare Traversable RT?			N/A		
			N/A	Landing Length (in)			N/A			N/A	DWS Provided?			N/A		
			N/A	Landing Width (in)			N/A			N/A	DWS Contrast?			N/A		
			N/A	Landing Slope (%)			N/A			N/A	DWS Length (in)			N/A		
			N/A	Landing X Slope (%)			N/A			N/A	DWS Full Width?			N/A		
Surveyor Notes:		N/A	N/A			N/A			N/A	DWS Offset (in)			N/A			
PROW/ADA:		R304.2.2, R304.5.3	N/A			N/A			N/A	Gutter Slope (%)			N/A			
			N/A			N/A			N/A	Gutter X Slope (%)			N/A			
			N/A			Yes			N/A	Painted X Walk2?			N/A			
			X Walk 1 Direction			To W				X Walk 2 Direction			N/A			
			N/A			123.0			N/A	X Walk 2 Width (in)			N/A			
						6.0				X Walk 2 Slope (%)			N/A			
						7.0				X Walk 2 X Slope (%)			N/A			
			N/A			Yes			N/A	Ramp inside XWalk2?			N/A			
						N/A			N/A	Clear Space?			N/A			
						N/A			N/A	Clear Space to XWalk (in)			N/A			
			N/A			N/A			N/A	Storm Grate/Utility Hazard?			N/A			
										Storm Grate/Utility Type						
									N/A				N/A			
									Yes	Surface Condition? (G/P)			Good			
Street 1 Name		ELM LN														
Stop Condition-Street 2		Signal														
Street 2 Name		N/A														
Stop Condition-Street 1		N/A														
Total Cost:		\$ 1850.00														

Total Cost: \$ 1850.00

