


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 12887	Main Street: CRAIGWOOD_DR	Cross Street: HICKORY_GROVE_RD	Location: NW
ADA ID: 0E1403C7E153	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 12.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance									
	Possible Solutions:		Compliance			Description			Data			
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)		48.5		No	Ramp Slope (%)		9.3	
			Yes	Ramp Width (in)		52.0		Yes	Ramp XSlope (%)		1.8	
			N/A	Flare Type LT		N/A		N/A	Flare Type RT		N/A	
			N/A	Flare Slope LT (%)		N/A		N/A	Flare Slope RT (%)		N/A	
			N/A	Flare Traversable LT?		N/A		N/A	Flare Traversable RT?		N/A	
			N/A	Landing Length (in)		N/A		N/A	DWS Provided?		N/A	
			N/A	Landing Width (in)		N/A		N/A	DWS Contrast?		N/A	
			N/A	Landing Slope (%)		N/A		N/A	DWS Length (in)		N/A	
			N/A	Landing X Slope (%)		N/A		N/A	DWS Full Width?		N/A	
Surveyor Notes:		N/A			N/A			DWS Offset (in)			N/A	
PROW/ADA:		R304.2.2			N/A							
					N/A			Gutter Ponding?			N/A	
					N/A			Gutter Lip Ht (in)			N/A	
					N/A			Painted X Walk1?			No	
					To S			X Walk 2 Direction			N/A	
					N/A			X Walk 2 Width (in)			N/A	
					2.6			X Walk 2 Slope (%)			N/A	
					1.3			X Walk 2 X Slope (%)			N/A	
					N/A			Ramp inside XWalk2?			N/A	
					N/A			Clear Space?			N/A	
					N/A			Clear Space to XWalk (in)			N/A	
					N/A			Storm Grate/Utility Hazard?			N/A	
								Storm Grate/Utility Type				
					N/A						N/A	
								Yes			Surface Condition? (G/P)	
											Good	

