

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                         |                                   |                        |
|------------------------|-------------------------|-----------------------------------|------------------------|
| Intersection ID: 19325 | Main Street: KREFELD_DR | Cross Street: MARGARET_WALLACE_RD | Location: W            |
| ADA ID: 0E2F94D3D375   | Ramp Type: ParaDiag     | Initial Pass/Fail: Pass           | Overall Compliance: No |
|                        |                         | Severity Score: 0.25              |                        |

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.**

Surveyor Notes:

**RT RP < 5%**

PROW/ADA:

**R304.5.3, R304.2.2-Perp, R304.3.2-Para**

Total Cost: \$ 3950.00

| Compliance | Description          | Data  | Compliance | Description                 | Data  |
|------------|----------------------|-------|------------|-----------------------------|-------|
| N/A        | Ramp Length LT (in)  | 90.5  | N/A        | Ramp Length RT (in)         | 55.0  |
| Yes        | Ramp Width LT (in)   | 74.0  | Yes        | Ramp Width RT (in)          | 62.0  |
| Yes        | Ramp Slope LT (%)    | 7.7   | Yes        | Ramp Slope RT (%)           | 4.5   |
| No         | Ramp XSlope LT (%)   | 4.6   | Yes        | Ramp XSlope RT (%)          | 0.2   |
| Yes        | Landing Length (in)  | 67.0  | Yes        | DWS Provided?               | Yes   |
| Yes        | Landing Width (in)   | 53.0  | Yes        | DWS Contrast?               | Yes   |
| No         | Landing Slope (%)    | 3.4   | Yes        | DWS Length (in)             | 25.5  |
| No         | Landing X Slope (%)  | 6.7   | Yes        | DWS Full Width?             | Yes   |
| N/A        | Landing Curb? (Y/N)  | No    | Yes        | DWS Offset (in)             | 0.0   |
| N/A        | Shared Landing?      | No    |            |                             |       |
| Yes        | Gutter Ponding?      | No    | Yes        | Gutter Slope (%)            | 4.2   |
| Yes        | Gutter Lip Ht (in)   | 0.0   | No         | Gutter X Slope (%)          | 5.6   |
| N/A        | Painted X Walk1?     | No    | N/A        | Painted X Walk2?            | No    |
|            | X Walk 1 Direction   | To SE |            | X Walk 2 Direction          | To NE |
| N/A        | X Walk 1 Width (in)  | N/A   | N/A        | X Walk 2 Width (in)         | N/A   |
|            | X Walk 1 Slope (%)   | 3.7   |            | X Walk 2 Slope (%)          | 0.2   |
|            | X Walk 1 X Slope (%) | 3.9   |            | X Walk 2 X Slope (%)        | 6.3   |
| N/A        | Ramp inside XWalk1?  | N/A   | N/A        | Ramp inside XWalk2?         | N/A   |
|            | Road Slope (%)       | 5.2   | N/A        | Clear Space?                | Yes   |
|            | Road X Slope (%)     | 2.2   | N/A        | Clear Space to XWalk (in)   | N/A   |
| Yes        | Any Obstructions?    | No    | Yes        | Storm Grate/Utility Hazard? | No    |
|            | Obstruction Type     |       |            | Storm Grate/Utility Type    |       |
|            |                      | N/A   |            |                             | N/A   |
|            |                      |       | Yes        | Surface Condition? (G/P)    | Good  |
|            |                      |       | N/A        | Curb Slope (%)              | 0.1   |

