

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

66.0

60.0

2.6

2.8

3.2

9.7

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: N/A Main Street: NINA DR Cross Street: W T HARRIS BV Location: SW **Overall Compliance: No** ADA ID: 0E665380D93F Ramp Type: Combination1 Initial Pass/Fail: Fail Severity Score: 58.75

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp XSlope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Flare Traversable LT?

Flare Type LT

N/A

Yes

No

Yes

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

No

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Curb Slope (%)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

65.0

61.0

14.2

1.7

61.0

43.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A



StopSign Street 1 Name Stop Condition-Street 1 NINA DR N/A Street 2 Name Stop Condition-Street 2 N/A

Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: RT RP < 5% PROW/ADA Not Found, R304.5.1, R304.5.3, R304.3.2

Total Cost:



1800.00

N/A Shared Landing? N/A N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A N/A Painted X Walk1? No Painted X Walk2? N/A To N N/A X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A 2.5 X Walk 2 Slope (%) N/A X Walk 1 Slope (%) X Walk 1 X Slope (%) 8.4 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk1? N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 7.1

