


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 17464		Main Street: FALLS_CREEK_LN		Cross Street: SCALEYBARK_RD		Location: E																																																																																																																																																									
ADA ID: 0E83FD23D642		Ramp Type: Directional1		Initial Pass/Fail: Pass		Overall Compliance: No		Severity Score: 0																																																																																																																																																							
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance																																																																																																																																																											
<div></div> <div>Possible Solutions: Remove & Replace Entire Ramp. Remove & Replace Gutter.</div> <div>Surveyor Notes: N/A</div> <div>PROW/ADA: Not Found, R305.2, R304.5.3</div> <table><tr><th>Compliance</th><th>Description</th><th>Data</th><th>Compliance</th><th>Description</th><th>Data</th></tr><tr><td>N/A</td><td>Ramp Length (in)</td><td>88.0</td><td>Yes</td><td>Grade Break?</td><td>Yes</td></tr><tr><td>Yes</td><td>Ramp Width (in)</td><td>72.0</td><td>Yes</td><td>Grade Break Slope (%)</td><td>3.1</td></tr><tr><td>Yes</td><td>Ramp Slope (%)</td><td>4.4</td><td>Yes</td><td>Grade Break XSlope (%)</td><td>1.8</td></tr><tr><td>Yes</td><td>Ramp XSlope (%)</td><td>1.4</td><td></td><td></td><td></td></tr><tr><td>N/A</td><td>Flare Type LT</td><td>N/A</td><td>N/A</td><td>Flare Type RT</td><td>N/A</td></tr><tr><td>N/A</td><td>Flare Slope LT (%)</td><td>N/A</td><td>N/A</td><td>Flare Slope RT (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Flare Traversable LT?</td><td>N/A</td><td>N/A</td><td>Flare Traversable RT?</td><td>N/A</td></tr><tr><td>Yes</td><td>Landing Length (in)</td><td>48.0</td><td>Yes</td><td>DWS Provided?</td><td>Yes</td></tr><tr><td>Yes</td><td>Landing Width (in)</td><td>71.5</td><td>Yes</td><td>DWS Contrast?</td><td>Yes</td></tr><tr><td>Yes</td><td>Landing Slope (%)</td><td>1.3</td><td>Yes</td><td>DWS Length (in)</td><td>24.0</td></tr><tr><td>Yes</td><td>Landing X Slope (%)</td><td>1.6</td><td>Yes</td><td>DWS Full Width?</td><td>Yes</td></tr><tr><td>N/A</td><td>Landing Curb? (Y/N)</td><td>No</td><td>No</td><td>DWS Offset LT (in)</td><td>68.0</td></tr><tr><td>N/A</td><td>Shared Landing?</td><td>No</td><td>Yes</td><td>DWS Offset RT (in)</td><td>0.0</td></tr><tr><td>Yes</td><td>Gutter Ponding?</td><td>No</td><td>Yes</td><td>Gutter Slope (%)</td><td>3.1</td></tr><tr><td>Yes</td><td>Gutter Lip Ht (in)</td><td>0.0</td><td>No</td><td>Gutter X Slope (%)</td><td>4.2</td></tr><tr><td>N/A</td><td>Painted X Walk1?</td><td>No</td><td></td><td>Road Slope (%)</td><td>2.2</td></tr><tr><td></td><td>X Walk 1 Direction</td><td>To NW</td><td></td><td>Road X Slope (%)</td><td>2.5</td></tr><tr><td></td><td>X Walk 1 Width (in)</td><td>N/A</td><td></td><td>Clear Space?</td><td>Yes</td></tr><tr><td></td><td>X Walk 1 Slope (%)</td><td>2.2</td><td>N/A</td><td>Clear Space to XWalk (in)</td><td>N/A</td></tr><tr><td></td><td>X Walk 1 X Slope (%)</td><td>2.5</td><td>Yes</td><td>Storm Grate/Utility Hazard?</td><td>No</td></tr><tr><td>N/A</td><td>Ramp inside XWalk1?</td><td>N/A</td><td></td><td>Storm Grate/Utility Type</td><td></td></tr><tr><td>Yes</td><td>Any Obstructions?</td><td>No</td><td></td><td></td><td>N/A</td></tr><tr><td></td><td>Obstruction Type</td><td></td><td>Yes</td><td>Surface Condition? (G/P)</td><td>Good</td></tr><tr><td></td><td></td><td></td><td>N/A</td><td>Curb Slope (%)</td><td>18.3</td></tr></table>				Compliance	Description	Data	Compliance	Description	Data	N/A	Ramp Length (in)	88.0	Yes	Grade Break?	Yes	Yes	Ramp Width (in)	72.0	Yes	Grade Break Slope (%)	3.1	Yes	Ramp Slope (%)	4.4	Yes	Grade Break XSlope (%)	1.8	Yes	Ramp XSlope (%)	1.4				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes	Yes	Landing Width (in)	71.5	Yes	DWS Contrast?	Yes	Yes	Landing Slope (%)	1.3	Yes	DWS Length (in)	24.0	Yes	Landing X Slope (%)	1.6	Yes	DWS Full Width?	Yes	N/A	Landing Curb? (Y/N)	No	No	DWS Offset LT (in)	68.0	N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	0.0	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.1	Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	4.2	N/A	Painted X Walk1?	No		Road Slope (%)	2.2		X Walk 1 Direction	To NW		Road X Slope (%)	2.5		X Walk 1 Width (in)	N/A		Clear Space?	Yes		X Walk 1 Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A		X Walk 1 X Slope (%)	2.5	Yes	Storm Grate/Utility Hazard?	No	N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		Yes	Any Obstructions?	No			N/A		Obstruction Type		Yes	Surface Condition? (G/P)	Good				N/A	Curb Slope (%)	18.3	Total Cost: \$ 2350.00					
				Compliance	Description	Data	Compliance	Description	Data																																																																																																																																																						
				N/A	Ramp Length (in)	88.0	Yes	Grade Break?	Yes																																																																																																																																																						
				Yes	Ramp Width (in)	72.0	Yes	Grade Break Slope (%)	3.1																																																																																																																																																						
				Yes	Ramp Slope (%)	4.4	Yes	Grade Break XSlope (%)	1.8																																																																																																																																																						
				Yes	Ramp XSlope (%)	1.4																																																																																																																																																									
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A																																																																																																																																																						
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A																																																																																																																																																						
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A																																																																																																																																																						
				Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes																																																																																																																																																						
				Yes	Landing Width (in)	71.5	Yes	DWS Contrast?	Yes																																																																																																																																																						
				Yes	Landing Slope (%)	1.3	Yes	DWS Length (in)	24.0																																																																																																																																																						
				Yes	Landing X Slope (%)	1.6	Yes	DWS Full Width?	Yes																																																																																																																																																						
				N/A	Landing Curb? (Y/N)	No	No	DWS Offset LT (in)	68.0																																																																																																																																																						
				N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	0.0																																																																																																																																																						
				Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.1																																																																																																																																																						
				Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	4.2																																																																																																																																																						
				N/A	Painted X Walk1?	No		Road Slope (%)	2.2																																																																																																																																																						
					X Walk 1 Direction	To NW		Road X Slope (%)	2.5																																																																																																																																																						
					X Walk 1 Width (in)	N/A		Clear Space?	Yes																																																																																																																																																						
					X Walk 1 Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A																																																																																																																																																						
					X Walk 1 X Slope (%)	2.5	Yes	Storm Grate/Utility Hazard?	No																																																																																																																																																						
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type																																																																																																																																																							
				Yes	Any Obstructions?	No			N/A																																																																																																																																																						
					Obstruction Type		Yes	Surface Condition? (G/P)	Good																																																																																																																																																						
							N/A	Curb Slope (%)	18.3																																																																																																																																																						

