

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18576 Main Street: WAKEFIELD_DR Cross Street: PINEHURST_PL Location: NE

ADA ID: 0EA88989D0F3 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

PINEHURST PL StopSign WAKEFIELD DR None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3

Total Cost: \$ 3200.00

r icia measarements/component compnance							
	Compliance Description		Data	Compliance		Description	Data
	N/A	Ramp Length (in)	31.0	Yes	Ramp	Slope (%)	5.7
	Yes	Ramp Width (in)	48.0	No	Ramp	XSlope (%)	5.4
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutter	Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter	X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No
		X Walk 1 Direction	To NW		X Wall	k 2 Direction	To S
	N/A	X Walk 1 Width (in)	N/A	N/A	X Wall	k 2 Width (in)	N/A
		X Walk 1 Slope (%)	5.3		X Wall	k 2 Slope (%)	2.6
		X Walk 1 X Slope (%)	3.1		X Wall	k 2 X Slope (%)	4.8
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
		Road Slope (%)	5.0	N/A	Clear	Space?	N/A
		Road X Slope (%)	0.6	N/A	Clear	Space to XWalk (in)	N/A

N/A N/A

N/A

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

N/A

Good







N/A

Any Obstructions?

Obstruction Type