## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10040974 Main Street: WALSH BV Cru					cross Street: N/A Location:				
	Main Street: WALSH_BV			Cross Street: N/A					S
ADA ID: 0EAA16CB0F9C Ramp Type: PerpDiag			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	58.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description Data		
The state of the s		Remove & Replace Curb Ram	p With	N/A	Ramp Length (in)	59.0	No	Ramp Slope (%)	13.5
		Two New Directional Ramps of		No	Ramp Width (in)	36.0	No	Ramp XSlope (%)	8.6
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
1 - Carl				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
6. 12				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
the second se		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	AN THE			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
Sheer 1 1	11	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Mars /		Not Found, R304.5.1, R304.2.	2,	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
12 11		R304.5.3	,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE				X Walk 1 Slope (%)	4.6		X Walk 2 Slope (%)	6.8
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	7.5		X Walk 2 X Slope (%)	2.2
Street 2 Name	WALSH BV			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	5.3	N/A	Clear Space?	N/A
					Road X Slope (%)	3.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P) Good

