

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

N/A

0.0

0.0

N/A

0.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

2.7

1.1

N/A

N/A

N/A

N/A

Poor

10.7

Intersection ID: 14258 Main Street: BERKELEY AV **Cross Street: LAFAYETTE AV** Location: NE Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 0EC670A76A07 Ramp Type: Directional1 Severity Score: 16.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

N/A

No

N/A N/A

Compliance Description

Grade Break?

Flare Type RT

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset LT (in)

DWS Offset RT (in)

Gutter Slope (%)

Road Slope (%)

Clear Space?

Curb Slope (%)

Road X Slope (%)

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Gutter X Slope (%)

Flare Traversable RT?

Grade Break Slope (%)

Grade Break XSlope (%)

Data

68.0

62.0

5.5

2.6

N/A

N/A

N/A

0.0

0.0

0.0

0.0

N/A

N/A

0.0

0.0

No

To W

N/A

2.7

1.1

N/A

N/A

Flare Traversable LT?

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Any Obstructions?

**Obstruction Type** 



**LAFAYETTE AV** Street 1 Name Stop Condition-Street 1 StopSign N/A Street 2 Name Stop Condition-Street 2 N/A

Possible Solution		Field Me
Possible Solutions:	Compl	iance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
·	Yes	Ramp Width (in)
	Yes	Ramp Slope (%)
	No	Ramp XSlope (%)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
Surveyor Notes:	N/A	Flare Traversable L1
DAMAGED CURB/RAMP	N/A	Landing Length (in)
	N/A	Landing Width (in)
	N/A	Landing Slope (%)
	N/A	Landing X Slope (%
PROW/ADA:	N/A	Landing Curb? (Y/N
R304.5.3, R302.7	N/A	Shared Landing?
	N/A	Gutter Ponding?
	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
		X Walk 1 Width (in)
		X Walk 1 Slope (%)
		V M-II. 4 V Class - (0)





Total Cost:



N/A

N/A

1600.00