

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Curb Slope (%)

Good

13.1

			`	/							
Intersection ID: 26567	Main Street: KUYKENDALL_RD				eet:	WHITE_HEMLOCK_LN	Location:	SW			
ADA ID: 0ED394017FCF	Ramp Type: Combination1			Initial Pass/Fail: Fail Overall Compliance				nce: N	o Severity Score:	22.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
Possible Solutions:				Compliance Description Da			Data	Data Compliance Description			
	Sec. There are	Remove & Replace Er	ntire Ramp.	N	/ A	Ramp Length LT (in)	73.5	N/A	Ramp Length RT (in)	43.0	
A State of the second s	Company of the second second	•	•	N	0	Ramp Width LT (in)	45.0	No	Ramp Width RT (in)	45.0	
A CALL OF A CALL	CARLAN STAN			Ye	es	Ramp Slope LT (%)	4.3	No	Ramp Slope RT (%)	10.7	
A A A A A A A A A A A A A A A A A A A	The second			N	0	Ramp XSlope LT (%)	5.0	No	Ramp XSlope RT (%)	3.3	
TONIL RD	8			N	/ A	Ramp Length (in)	71.0	No	Ramp Slope (%)	8.4	
KUNKAEKIOA				N	0	Ramp Width (in)	38.0	No	Ramp XSlope (%)	4.9	
and the state of t		Surveyor Notes:		N	/ A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
the second secon		LT RP < 5%		N	/ A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
A REAL MARKED				N	/ A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N	/ A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	E me			N	/ A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	110000	PROW/ADA:		N	/ A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
AND AND AND AND	1	Not Found, R304.5.1,	R304.5.1,	N	/ A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		R304.2.2, R304.5.3, R3		N	/ A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
HA CA				N	/ A	Shared Landing?	N/A				
				N	/ A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	StopSign			N/	/ A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	WHITE HEMLOCK LN			N	/ A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	4.6		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	6.2		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$ 180	0.00 N	/ A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					in the			N/A	Any Obstruction?	N/A	
			- Well-						Obstruction Type		
										N/A	
								N/A	Storm Grate/Utility Hazard?	N/A	
and the second second									Storm Grate/Utility Type	11/2	
										N/A	
										• •	