

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18245 Main Street: HASSELL_PL Cross Street: SELWYN_AV Location: NE

ADA ID: 0ED585B6FBA7 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
SELWYN AV
Stop Condition-Street 2
None
Street 2 Name
HASSELL PL
Stop Condition-Street 1
StopSign

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2

| Comp | liance Description | Data | Comp | liance | Description | Data |
|-------|-----------------------|------|------|--------|-------------------------|------|
| N/A | Ramp Length (in) | 35.0 | No | Ramp | Slope (%) | 9.5 |
| No | Ramp Width (in) | 43.0 | Yes | Ramp | XSlope (%) | 1.0 |
| N/A | Flare Type LT | N/A | N/A | Flare | Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare | Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare | Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | N/A | DWS | Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS | Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS | Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS | Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS | Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutte | r Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutte | r X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Paint | ed X Walk2? | No |
| | X Walk 1 Direction | To W | | X Wa | lk 2 Direction | To S |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Wa | lk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 1.5 | | X Wa | lk 2 Slope (%) | 1.0 |
| | X Walk 1 X Slope (%) | 0.2 | | X Wa | lk 2 X Slope (%) | 2.5 |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ram | inside XWalk2? | N/A |
| | Road Slope (%) | 1.8 | N/A | Clear | Space? | N/A |
| | Road X Slope (%) | 1.6 | N/A | Clear | Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storn | n Grate/Utility Hazard? | N/A |
| | Obstruction Type | | l | Storn | n Grate/Utility Type | |
| | | N/A | | | | N/A |
| | | | Yes | Surfa | ce Condition? (G/P) | Good |
| The . | | | | | | |





Total Cost:



3200.00