

Intersection ID: 10345		Main Street: COBURG_AV		Cross Street: RUTH_DR		Location:		NW									
ADA ID: 0EEEE2DAD460		Ramp Type: Directional1		Initial Pass/Fail: Pass		Overall Compliance: No		Severity Score: 15									
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance													
 Possible Solutions: Remove & Replace Entire Ramp. Remove & Replace Gutter. Surveyor Notes: N/A PROW/ADA: R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305.1.4, R305.2, R302.7, R302.7.2, R304.5.4 <table><tr><td>Street 1 Name</td><td>COBURG AV</td></tr><tr><td>Stop Condition-Street 1</td><td>StopSign</td></tr><tr><td>Street 2 Name</td><td>N/A</td></tr><tr><td>Stop Condition-Street 2</td><td>N/A</td></tr></table> Total Cost: \$ 2350.00				Street 1 Name	COBURG AV	Stop Condition-Street 1	StopSign	Street 2 Name	N/A	Stop Condition-Street 2	N/A	Compliance	Description	Data	Compliance	Description	Data
				Street 1 Name	COBURG AV												
				Stop Condition-Street 1	StopSign												
				Street 2 Name	N/A												
				Stop Condition-Street 2	N/A												
				N/A	Ramp Length (in)	70.5	N/A	Grade Break?	N/A								
				Yes	Ramp Width (in)	60.0	N/A	Grade Break Slope (%)	0.0								
				Yes	Ramp Slope (%)	3.8	N/A	Grade Break XSlope (%)	0.0								
				Yes	Ramp XSlope (%)	1.5											
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A								
N/A	Flare Slope LT (%)	9.2	N/A	Flare Slope RT (%)	3.3												
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No												
Yes	Landing Length (in)	52.0	Yes	DWS Provided?	Yes												
Yes	Landing Width (in)	60.0	Yes	DWS Contrast?	Yes												
No	Landing Slope (%)	6.5	Yes	DWS Length (in)	24.0												
No	Landing X Slope (%)	2.3	No	DWS Full Width?	No												
N/A	Landing Curb? (Y/N)	No	No	DWS Offset LT (in)	84.0												
N/A	Shared Landing?	No	No	DWS Offset RT (in)	33.0												
No	Gutter Ponding?	Yes	No	Gutter Slope (%)	14.2												
No	Gutter Lip Ht (in)	0.5	No	Gutter X Slope (%)	3.3												
N/A	Painted X Walk1?	No		Road Slope (%)	6.5												
	X Walk 1 Direction	To SE		Road X Slope (%)	1.3												
	X Walk 1 Width (in)	N/A		Clear Space?	Yes												
	X Walk 1 Slope (%)	6.5	N/A	Clear Space to XWalk (in)	N/A												
	X Walk 1 X Slope (%)	1.3	Yes	Storm Grate/Utility Hazard?	No												
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type													
Yes	Any Obstructions?	No			N/A												
	Obstruction Type		Yes	Surface Condition? (G/P)	Good												
			N/A	Curb Slope (%)	N/A												

