## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		(-	<b>0</b> 11 N		/						
Intersection ID: 10041343	Main Stre	Main Street: WEST_BV			Street:	N/A	Location:	SE			
ADA ID: 0F003BD08A70	Ramp Ty	ype: Combination1Diag			Initial Pass/Fail: Fail Overall Compliance				o Severity Score:	0	
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance											
Rest BY		Possible Solutions:							liance Description	Data	
		Remove & Replace Curb	Ram	o With	N/A	Ramp Length LT (in)	52.0	N/A	Ramp Length RT (in)	58.0	
	EV.	Two New Directional Ram	al Ramps or		Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	60.0	
		Equivalent. Remove & Replace Sidewalk.	place	)	No	Ramp Slope LT (%)	10.1	Yes	Ramp Slope RT (%)	3.3	
				Yes	Ramp XSlope LT (%)	0.3	No	Ramp XSlope RT (%)	2.1		
				N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	4.6		
	-				Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.6	
	PL.	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	- AL	RT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	·				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	THE A	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		R304.3.2, R304.5.3			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	XE. TX				N/A	Shared Landing?	N/A				
	and and				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	WEST BV				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
Street 2 Name	None					X Walk 1 Direction	To N		X Walk 2 Direction	To W	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	2.3	
						X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	0.3	
		Total Cost:	\$	3600.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	0.9		Clear Space?	N/A	
						Road X Slope (%)	1.6	N/A	Clear Space to XWalk (in)	N/A	
N/A						N/A	Any Obstruction?	N/A			
						Ama			Obstruction Type	N/A	

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A

Yes	Surface Condition? (G/P)	Good
	Curb Slope (%)	1.8



