


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 5778	Main Street: JOHN_KIRK_DR	Cross Street: MARGIE_ANN_DR	Location: S
ADA ID: 0F1591C18F1A	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	50.0
			Yes	Ramp Width (in)	48.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.2.2, R304.5.3</p>			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
		N/A	Gutter Lip Ht (in)	N/A	
		N/A	Painted X Walk1?	No	
			X Walk 1 Direction	To NW	
		N/A	X Walk 1 Width (in)	N/A	
			X Walk 1 Slope (%)	3.3	
			X Walk 1 X Slope (%)	2.3	
		N/A	Ramp inside XWalk1?	N/A	
			Road Slope (%)	N/A	
			Road X Slope (%)	N/A	
		N/A	Any Obstructions?	N/A	
			Obstruction Type		
				N/A	N/A
				Yes	Surface Condition? (G/P) Good
Street 1 Name		MARGIE ANN DR			
Stop Condition-Street 2		None			
Street 2 Name		N/A			
Stop Condition-Street 1		N/A			
Total Cost:		\$ 1850.00			