


Intersection ID: 11527	Main Street: BARRY_ST	Cross Street: GRACE_ST	Location:	NE
ADA ID: 0F2F7B0BE4A7	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 60

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	52.0	No	Ramp Slope (%)	10.6
			No	Ramp Width (in)	26.0	No	Ramp XSlope (%)	6.8
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Street 1 Name	BARRY ST		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	Stop Condition-Street 2		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	Street 2 Name		N/A	Shared Landing?	N/A			
	Stop Condition-Street 1		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To W		X Walk 2 Direction	To S
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	6.6
				X Walk 1 X Slope (%)	4.2		X Walk 2 X Slope (%)	3.3
PROW/ADA:		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Not Found, R304.5.1, R304.2.2, R304.5.3		N/A	Road Slope (%)	4.6	N/A	Clear Space?	N/A	
			Road X Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
			Obstruction Type			Storm Grate/Utility Type		
				N/A			N/A	
					Yes	Surface Condition? (G/P)	Good	
Total Cost:		\$ 3200.00						

