


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 9907	Main Street: RUTH_DR	Cross Street: SHANNONHOUSE_DR	Location: W
ADA ID: 0F8076F220C2	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 12.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		No	Ramp Slope (%)	10.9
			Yes	Ramp Width (in)	1.6
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.2.2</p>			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			Yes	Gutter Slope (%)	N/A
			1.0	Gutter X Slope (%)	N/A
			No	Painted X Walk2?	N/A
			To S	X Walk 2 Direction	N/A
			N/A	X Walk 2 Width (in)	N/A
			0.6	X Walk 2 Slope (%)	N/A
			1.4	X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk2?	N/A
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Storm Grate/Utility Type	N/A
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good
Total Cost:		\$ 1850.00			

