


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 9158	Main Street: MORETZ_AV	Cross Street: RACHEL_ST	Location: NW
ADA ID: 0FBF4A9DA1F8	Ramp Type: Para	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 1.25	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	69.0
			Yes	Ramp Width LT (in)	60.0
			Yes	Ramp Slope LT (%)	2.8
			No	Ramp XSlope LT (%)	2.7
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
<p>Surveyor Notes:</p> <p>LT RP < 5%, RT RP < 5%</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.3</p>			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To SE
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	0.7
				X Walk 1 X Slope (%)	3.3
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	N/A
<p>Street 1 Name</p> <p>Stop Condition-Street 1</p> <p>Street 2 Name</p> <p>Stop Condition-Street 2</p>			N/A	Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			N/A		N/A
					N/A
			Yes	Surface Condition? (G/P)	Good
				Replace Curb Slope (%)	36.7
Total Cost:		\$ 1600.00			

