cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

0.8

Intersection ID: 14183	Main Street: WEST_BV			Cross	Street:	OLD_STEEL	Location:	SW		
ADA ID: 10473745F99B	Ramp Ty	Ramp Type: ParaDiag			Pass/Fa	ail: Pass	o Severity Score:	10.25		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	6	Possible Solutions:			Compliance Description			Data Compliance Description		
		Remove & Replace Curb	Rame	With	N/A	Ramp Length L	_T (in) 38.0	N/A	Ramp Length RT (in)	48.0
The I B mark		Two New Directional Ram			Yes	Ramp Width L1	. ,	Yes	Ramp Width RT (in)	59.0
19 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Equivalent.	•		Yes	Ramp Slope L1	Г (%) 6.0	Yes	Ramp Slope RT (%)	7.5
For the second					No	Ramp XSlope I		No	Ramp XSlope RT (%)	2.7
HOLE		Surveyor Notes:			Yes	Landing Length	. ,		DWS Provided?	No
WESILE					Yes	Landing Width	()		DWS Contrast?	No
					No	Landing Slope			DWS Length (in)	N/A
		RAMP PAVERS			Yes	Landing X Slop	()		DWS Full Width?	No
the state of the		RAMF FAVERS			N/A	Landing Curb?			DWS Offset (in)	N/A
the formation of the				N/A	Shared Landing			Dwo onset (iii)	10/2	
				Yes	Gutter Ponding	•		Gutter Slope (%)	1.7	
2	PROW/ADA:			Yes	Gutter Lip Ht (in	-		Gutter X Slope (%)	0.3	
						,		,		
	R304.5.3, R304.2.2-Perp, R304.3.2-		3.2-	N/A	Painted X Walk		N/A	Painted X Walk2?	No Ta N	
Para, R305						X Walk 1 Direct			X Walk 2 Direction	To N
				N/A	X Walk 1 Width	()	N/A	X Walk 2 Width (in)	N/A	
					X Walk 1 Slope			X Walk 2 Slope (%)	1.3	
	LD STEELE CREEK RD					X Walk 1 X Slo	,		X Walk 2 X Slope (%)	0.1
Stop Condition-Street 1	Signal				Yes	Ramp inside X	Walk1? Yes	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	WEST BV					Road Slope (%	o) 1.0	N/A	Clear Space?	Yes
Stop Condition-Street 2	Signal					Road X Slope ((%) 1.8	N/A	Clear Space to XWalk (in)	N/A
					Yes	Any Obstructio	ns? No	Yes	Storm Grate/Utility Hazard?	No
						Obstruction Type	ре		Storm Grate/Utility Type	
		Total Cost:	\$	3200.00			N/A			N/A
								Yes	Surface Condition? (G/P)	Good

