

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 15254	Main Street: IDEAL_WY	Cross Street: PARK_RD	Location: SW
ADA ID: 10648F61FEB3	Ramp Type: BlendTrans2	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 25	

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Install Detectable Warning System.  
Restripe Crosswalk(s) To Provide  
Clear space. Grind Gutter Lip.**

Surveyor Notes:

**N/A**

PROW/ADA:

**Not Found, R305, R302.7.2**

Total Cost: \$ 935.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	93.0	Yes	BlendTrans Slope (%)	2.9
Yes	Ramp Width (in)	132.0	Yes	BlendTrans XSlope (%)	1.4
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
N/A	Flare Slope LT (%)	0.4	Yes	Flare Slope RT (%)	3.6
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	Yes
N/A	Landing Length (in)	N/A	No	DWS Provided?	No
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	No
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.7
No	Gutter Lip Ht (in)	1.0	Yes	Gutter X Slope (%)	1.3
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
	X Walk 1 Direction	To E		X Walk 2 Direction	To N
	X Walk 1 Width (in)	114.0		X Walk 2 Width (in)	108.0
	X Walk 1 Slope (%)	5.4		X Walk 2 Slope (%)	4.8
	X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	0.9
Yes	Ramp inside XWalk1?	Yes	Yes	Ramp inside XWalk2?	Yes
	Road Slope (%)	2.2		Clear Space?	Yes
	Road X Slope (%)	5.5	No	Clear Space to XWalk (in)	29.0
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			Yes	Curb Slope (%)	2.2

Street 1 Name PARK RD  
Stop Condition-Street 1 Signal  
Street 2 Name IDEAL WY  
Stop Condition-Street 2 Signal

