cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29336	Main Str	Main Street: NEVIN_BROOK_RD			WHITE_ROCK_CT	Location:	W		
ADA ID: 10E729020268	Ramp Ty	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				37.5
Codes/Mitigation Info/Possible Solution				hitial Pass/Fail: Fail Overall Compliance: No Severity Score: 37.5 Field Measurements/Component Compliance					
		Possible Solutions:						Compliance Description Data	
		Remove & Replace Curb Ram	n With	N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	8.7
		Two New Directional Ramps	•	Yes	Ramp Width (in)	101.0	No	Ramp XSlope (%)	7.6
		Equivalent.	<i>,</i>	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
- Marta				N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
DO				N/A	Landing Length (in)	N/A		DWS Provided?	N/A N/A
the				N/A		N/A	N/A	DWS Contrast?	N/A N/A
					Landing Width (in)				
		N/A		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
	A ANERT			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
	A	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Not Found, R304.2.2, R304.5.3			3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
	AND			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	NEVIN BROOK RD	-			X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	11.0
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	9.3		X Walk 2 X Slope (%)	5.4
Street 2 Name	WHITE ROCK CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	9.1	N/A	Clear Space?	N/A
					Road X Slope (%)	4.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	 N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00	11/2	Obstruction Type	17/4		Storm Grate/Utility Type	17/2
			3200.00		Obstruction Type	N1/A		Storm Grate/Otimity Type	N//A
						N/A			N/A

'es Surface Condition? (G/P)

Good

