

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15167 Main Street: GOLDFIELDS_DR Cross Street: OLDE_SAVANNAH_RD Location: SW

ADA ID: 10EEBE4C3C8E Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name GOLDSFIELD DR
Stop Condition-Street 2 None
Street 2 Name OLE SAVANNAH RD
Stop Condition-Street 1 StopSign

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance						
Comp	liance Description	Data	Compl	liance	Description	Data
N/A	Ramp Length (in)	47.0	No	Ramp	Slope (%)	8.5
Yes	Ramp Width (in)	48.0	No	Ramp	XSlope (%)	3.3
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No
	X Walk 1 Direction	To E		X Wa	lk 2 Direction	To N
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.0		X Wa	lk 2 Slope (%)	0.8
	X Walk 1 X Slope (%)	0.6		X Wa	lk 2 X Slope (%)	3.0
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	2.5	N/A	Clear	Space?	N/A
	Road X Slope (%)	2.3	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	Obstruction Type			Storm	Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good





