


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|---------------------------|----------------------|-------------------------|------------------------|
| Intersection ID: 10014727 | Main Street: ANNE_ST | Cross Street: N/A | Location: SW |
| ADA ID: 10FC4771D414 | Ramp Type: ParaDiag | Initial Pass/Fail: Fail | Overall Compliance: No |
| | | | Severity Score: 13.75 |

| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | |
|---|---|--|---|-----------------------------|-------------|
|  | Possible Solutions: | | Compliance | Description | Data |
| | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. | | N/A | Ramp Length LT (in) | 61.0 |
| | | | Yes | Ramp Width LT (in) | 54.0 |
| | | | Yes | Ramp Slope LT (%) | 6.2 |
| | | | No | Ramp XSlope LT (%) | 2.5 |
| | | | N/A | Landing Length (in) | N/A |
| | | | N/A | Landing Width (in) | N/A |
| | | | N/A | Landing Slope (%) | N/A |
| | | | N/A | Landing X Slope (%) | N/A |
| | | | N/A | Landing Curb? (Y/N) | N/A |
| <p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.3, R304.3.2</p> | | | N/A | Ramp XSlope RT (%) | 0.9 |
| | | | N/A | DWS Provided? | N/A |
| | | | N/A | DWS Contrast? | N/A |
| | | | N/A | DWS Length (in) | N/A |
| | | | N/A | DWS Full Width? | N/A |
| | | | N/A | DWS Offset (in) | N/A |
| | | | N/A | Gutter Slope (%) | N/A |
| | | | N/A | Gutter X Slope (%) | N/A |
| | | | N/A | Painted X Walk1? | No |
| | | | N/A | Painted X Walk2? | No |
| <p>Street 1 Name</p> <p>Stop Condition-Street 1</p> <p>Street 2 Name</p> <p>Stop Condition-Street 2</p> | | | N/A | X Walk 1 Direction | To E |
| | | | N/A | X Walk 2 Direction | To N |
| | | | N/A | X Walk 1 Width (in) | N/A |
| | | | N/A | X Walk 2 Width (in) | N/A |
| | | | N/A | X Walk 1 Slope (%) | 7.3 |
| | | | N/A | X Walk 2 Slope (%) | 2.3 |
| | | | N/A | X Walk 1 X Slope (%) | 1.7 |
| | | | N/A | X Walk 2 X Slope (%) | 2.8 |
| | | | N/A | Ramp inside XWalk1? | N/A |
| | | | N/A | Ramp inside XWalk2? | N/A |
| <p>Total Cost:</p> <p>\$ 3200.00</p> | | | N/A | Road Slope (%) | 0.2 |
| | | | N/A | Road X Slope (%) | 2.8 |
| | | | N/A | Any Obstructions? | N/A |
| | | | N/A | Obstruction Type | |
| | | | N/A | Storm Grate/Utility Hazard? | N/A |
| | | | N/A | Storm Grate/Utility Type | |
| | | | N/A | Surface Condition? (G/P) | Good |
| | | | N/A | Curb Slope (%) | 3.6 |
| | | | | | |
| | | | | | |

