

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9228 Main Stu	Main Street: FAIRMONT_ST		Cross Street: RENNER_ST			Location:	SE
			Initial Pass/Fail: Fail Overall Compliance: N				10
						10	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
	Possible Solutions:	Compliance Description		Data	Data Compliance Description		Data
A A A A A A A A A A A A A A A A A A A	Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	36.5	Yes	Ramp Slope (%)	7.9
		No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	4.6
REALER ST & REALER ST		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	8	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A			
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
R AND AND A			X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name RENNER ST			X Walk 1 Slope (%)	4.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 None			X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 1	850.00	Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A

Yes Surface Condition? (G/P)

Good

