


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 3928	Main Street: BICKHAM_LN	Cross Street: KIRKGARD_TL	Location: SW
ADA ID: 119C69004148	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 21.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	<b>Remove &amp; Replace Entire Ramp.</b>		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
<p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>R304.5.1, R304.2.2</b></p>			<b>N/A</b>	Ramp Length (in)	<b>63.0</b>
			<b>No</b>	Ramp Width (in)	<b>44.0</b>
			<b>No</b>	Ramp Slope (%)	<b>11.1</b>
			<b>Yes</b>	Ramp XSlope (%)	<b>0.9</b>
			<b>N/A</b>	Flare Type LT	<b>N/A</b>
			<b>N/A</b>	Flare Slope LT (%)	<b>N/A</b>
			<b>N/A</b>	Flare Traversable LT?	<b>N/A</b>
			<b>N/A</b>	Landing Length (in)	<b>0.0</b>
			<b>N/A</b>	Landing Width (in)	<b>0.0</b>
			<b>N/A</b>	Landing Slope (%)	<b>0.0</b>
			<b>N/A</b>	Landing X Slope (%)	<b>0.0</b>
			<b>N/A</b>	Landing Curb? (Y/N)	<b>N/A</b>
			<b>N/A</b>	Shared Landing?	<b>N/A</b>
			<b>N/A</b>	Gutter Ponding?	<b>0.0</b>
			<b>N/A</b>	Gutter Lip Ht (in)	<b>0.0</b>
			<b>N/A</b>	Painted X Walk1?	<b>No</b>
				X Walk 1 Direction	<b>To N</b>
				X Walk 1 Width (in)	<b>N/A</b>
				X Walk 1 Slope (%)	<b>3.7</b>
				X Walk 1 X Slope (%)	<b>4.9</b>
			<b>N/A</b>	Ramp inside XWalk1?	<b>N/A</b>
			<b>N/A</b>	Any Obstructions?	<b>N/A</b>
				Obstruction Type	
			<b>Yes</b>	Surface Condition? (G/P)	<b>Good</b>
			<b>N/A</b>	Curb Slope (%)	<b>9.1</b>
Street 1 Name	KIRKGARD TL				
Stop Condition-Street 1	StopSign				
Street 2 Name	N/A				
Stop Condition-Street 2	N/A				
Total Cost:	\$	1600.00			

