## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 45764	ntersection ID: 45764 Main Street: CHRISTENBURY RD				Cross Street: GREENOCK_RIDGE_CT				N
ADA ID: 11C6DDE91FA2				Initial Pass/Fail: Fail Overall Compliance: No				Location: o Severity Score:	
				ra55/re			21.25		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Network of the second sec	Possible Solutions:		Compliance Description Data C			Comp	Compliance Description	
A A A A A A A A A A A A A A A A A A A		Remove & Replace Curb Ramp Wi Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.6
A The second			r	No	Ramp Width (in)	42.0	No	Ramp XSlope (%)	5.9
All Art				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
MAR ANI				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
1 A A A		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
and the second s		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
AUGUST			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
the state of the state of the	G. C.	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	CHRISTENBURY RD	-			X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	8.2
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	7.3		X Walk 2 X Slope (%)	0.0
Street 2 Name	GREENOCK RIDGE CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	5.5	N/A	Clear Space?	N/A
	. •				Road X Slope (%)	2.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A		, ,,	N/A

Yes Surface Condition? (G/P)

Good

