cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 21737	Main Street: HUNTINGTOWNE_FARMS_LN Cross Street: PARK_RD							Location:	NE
ADA ID: 11D1F682258F					Initial Pass/Fail: Fail Overall Compliance: No				13.75
Codes/Mitigation Info/Possible Solution				Initial Pass/Fail: Fail Overall Compliance: No Severity Score: Field Measurements/Component Compliance					
		Possible Solutions:					liance Description	Data	
	N. Company	Remove & Replace Entire Ra	amp.	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	10.1
A A A A A A A A A A A A A A A A A A A				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.9
	いたい			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Nº An			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A REAL STREET	14 72			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	A PAR			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	No. 10 bill	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	1. 1.			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the states of th	ALL SALES			N/A	Shared Landing?	N/A			
	H. CAL	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
and the second s	1 10 . 40	Not Found, R304.2.2, R304.5	.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Provide the second seco	-	ē			X Walk 1 Direction	To W		X Walk 2 Direction	N/A
· an interest				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	PARK RD	_			X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

s Surface Condition? (G/P)

Good

