


Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 5638	Main Street: BELLHAVEN_BV	Cross Street: KENTBERRY_DR	Location: W
ADA ID: 120792104161	Ramp Type: Para	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 12.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	55.0
			Yes	Ramp Width LT (in)	72.5
			Yes	Ramp Slope LT (%)	5.8
			Yes	Ramp XSlope LT (%)	1.5
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
<p>Surveyor Notes:</p> <p>NO RT SW</p> <p>PROW/ADA:</p> <p>R304.3.2</p>			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To E
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	0.6
				X Walk 1 X Slope (%)	1.1
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	N/A
			N/A	Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	11.4
Total Cost:		\$ 1600.00			

