cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27431 Main Street: BALLANTYNE_COMMONS_PY Cross Street: RUSHMORE_DR								Location:	NW
ADA ID: 12B3455BD572	Ramp T	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
- Harris Martin		Possible Solutions:		Compliance Description			Data Compliance Description		Data
	ANY TS .	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	107.0	Yes	Ramp Slope (%)	5.1
	A. A.			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.3
	M. M. M.			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
/ WARDING BUT	1 4 //			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	1.8			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A ANDA	NY X			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A REAL WAR	R AL	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	S.	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A A A A A A A A A A A A A A A A A A A	Sold 2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	COM AND			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
6.	1 A And			N/A	Shared Landing?	N/A			
the the states	the states	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
State of the second sec	A CONT	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	A A A A			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
5 / / / / E	The second second				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
Set 1 - Al - Long to	State Charles			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	RUSHMORE DR				X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

