

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

62.0

59.0

9.2

1.5

8.5

6.6

N/A

No

To E

N/A

0.3

3.2

N/A

Intersection ID: 21396 Main Street: W ARROWOOD RD **Cross Street: FOREST PINE DR** Location: NW **Overall Compliance: No ADA ID: 12C9BCC1A48B** Ramp Type: Combination2Diag Initial Pass/Fail: Fail **Severity Score:** 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

Yes

Nο

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Flare Traversable RT?

Data

N/A

N/A

N/A

N/A

47.0

41.5

N/A

No

N/A

3.2

0.7

N/A

To SE



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

None W ARROWOOD RD StopSign FOREST PINE DR Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: **MEDIAN ACROSS W ARROWOOD** RD PROW/ADA: R304.5.1, R304.2.2, R304.5.3, R304.3.2

Total Cost:

Compliance Description N/A Ramp Length LT (in) N/A Ramp Width LT (in) N/A Ramp Slope LT (%) N/A Ramp XSlope LT (%) N/A Ramp Length (in) No Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in)

N/A

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?



3200.00

2.3 Road Slope (%) Clear Space? N/A Road X Slope (%) 1.1 N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 2.4 Curb Slope (%)



