

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 15524	Main Street: SAM_DRENAN_RD	Cross Street: SANDLEWOOD_RD	Location: SE
ADA ID: 12D39DB6C58A	Ramp Type: ParaDiag	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 10.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3, R305

Total Cost: \$ 3950.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	79.0	N/A	Ramp Length RT (in)	70.0
Yes	Ramp Width LT (in)	58.0	Yes	Ramp Width RT (in)	63.0
Yes	Ramp Slope LT (%)	8.1	Yes	Ramp Slope RT (%)	5.5
No	Ramp XSlope LT (%)	2.3	Yes	Ramp XSlope RT (%)	0.1
Yes	Landing Length (in)	61.0	No	DWS Provided?	No
Yes	Landing Width (in)	50.0	N/A	DWS Contrast?	No
Yes	Landing Slope (%)	2.0	N/A	DWS Length (in)	N/A
No	Landing X Slope (%)	2.9	N/A	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	4.7
Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.6
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To N		X Walk 2 Direction	To SW
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.4		X Walk 2 Slope (%)	1.3
	X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	1.9
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	3.9	N/A	Clear Space?	Yes
	Road X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	8.1

Street 1 Name SAM DRENAN RD

Stop Condition-Street 1 None

Street 2 Name SANDLEWOOD RD

Stop Condition-Street 2 StopSign

