

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 11318	Main Street: GRANDIN_RD			Cross Street: W_4TH_ST_EXT					Location:	SE
ADA ID: 12F7BCBAC565	Ramp Type: Perp			Initial Pass/Fail: Pass Overall Compliance: Ye					es Severity Score:	0
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	Aller	Possible Solutions:		Compliance Description Data			Compliance Description Data		Data	
the Martin Contraction of the second se	JA SAD	N/A			N/A	Ramp Length (in)	84.0	Yes	Ramp Slope (%)	6.1
	一、 光保				Yes	Ramp Width (in)	70.0	Yes	Ramp XSlope (%)	0.6
a b	the set of				Yes	Flare Type LCurbed_NoWa	alkSurface	Yes	Flare Type RT	N/A
E G II	A				Yes	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
the states					N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
El a Carry Se	2 41				Yes	Landing Length (in)	72.5	Yes	DWS Provided?	Yes
6. 30		Surveyor Notes:			Yes	Landing Width (in)	70.0	Yes	DWS Contrast?	Yes
	1	N/A			Yes	Landing Slope (%)	1.1	Yes	DWS Length (in)	24.0
84 430					Yes	Landing X Slope (%)	1.3	Yes	DWS Full Width?	Yes
	S Parts				N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0
	A MARTIN				N/A	Shared Landing?	No			
A the Addition	Tartes	PROW/ADA:			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.0
	· · · · · · ·	N/A			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.7
PATA AND	14 1 1				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
6/2 -	· · · · /					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
A LAND AND AND AND AND AND AND AND AND AND					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	W 4TH ST EXT	-				X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	Yes
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost:	\$	0.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A