

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

8.5

1.7

N/A

N/A

Main Street: MODERN WY Intersection ID: 52627 **Cross Street: CORMWELL LN** Location: SE Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5 **ADA ID: 131FBC19B58A** Ramp Type: Perp

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

No

Yes

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

Data

104.0

58.0

N/A

N/A



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1

n ossible solution		i icia ivic
Possible Solutions:	Compl	iance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
	Yes	Ramp Width (in)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
	N/A	Flare Traversable L
	N/A	Landing Length (in)
Surveyor Notes:	N/A	Landing Width (in)
N/A	N/A	Landing Slope (%)
	N/A	Landing X Slope (%
	N/A	Landing Curb? (Y/N
	N/A	Shared Landing?
PROW/ADA:	N/A	Gutter Ponding?
Not Found, R304.2.2	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
	N/A	X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%
	N/A	Ramp inside XWalk
		Daniel Clause (0/ )





