cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 48197	Main Street: ARDREY_KELL_DR			reet:	BLANKENEY_PARK_D	Location:	NW			
ADA ID: 1356C693E01A	Ramp Type: PerpDiag			ss/Fa	ail: Fail Overall C	o Severity Score:	42.5			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:					liance Description	Data		
		Remove & Replace Curb Ramp W	/ith ^I	N/A	Ramp Length (in)	72.0	No	Ramp Slope (%)	13.3	
		Two New Directional Ramps or		No	Ramp Width (in)	35.0	Yes	Ramp XSlope (%)	0.6	
		Equivalent.	1	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	A Strates		1	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	and the second second		1	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
Contraction and a	1 The second		1	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	6.	Surveyor Notes:	1	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
to the second se		N/A	1	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
THE REPART OF THE	L_RD			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
ARDINES			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
			N/A	Shared Landing?	N/A					
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
and the second second and	the states	R304.5.1, R304.2.2	1	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
K304.3.1, K304.2.2				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To S		X Walk 2 Direction	To E	
			,	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	ARDREY KELL RD		-		X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	2.6	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	1.3	
Street 2 Name	ENTRANCE		,	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	StopSign		•		Road Slope (%)	1.3		Clear Space?	N/A	
	etepeign				Road X Slope (%)	4.3	N/A	Clear Space to XWalk (in)	N/A	
			1	N/A	Any Obstructions?	4.5 N/A		Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 32	200.00		Obstruction Type	174		Storm Grate/Utility Type	100	
1		ψ υ				N/A		Stern Grate/Starty Type	N/A	
						17/4			11/7	

Yes Surface Condition? (G/P)

Good

