


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10033236	Main Street: OAK_LAKE_BV	Cross Street: N/A	Location: E
ADA ID: 13E6552E926A	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 8.75	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	36.0	Yes
			No	Ramp Width (in)	46.0	Yes
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			N/A	Landing Length (in)	N/A	N/A
			N/A	Landing Width (in)	N/A	N/A
			N/A	Landing Slope (%)	N/A	N/A
			N/A	Landing X Slope (%)	N/A	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A
			N/A	Shared Landing?	N/A	
			N/A	Gutter Ponding?	N/A	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A
			N/A	Painted X Walk1?	No	N/A
				X Walk 1 Direction	To W	
			N/A	X Walk 1 Width (in)	N/A	N/A
				X Walk 1 Slope (%)	1.3	
				X Walk 1 X Slope (%)	1.0	
			N/A	Ramp inside XWalk1?	N/A	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1</p>				Ramp Slope (%)	5.3	
				Ramp XSlope (%)	1.4	
				Flare Type RT	N/A	
				Flare Slope RT (%)	N/A	
				Flare Traversable RT?	N/A	
				DWS Provided?	N/A	
				DWS Contrast?	N/A	
				DWS Length (in)	N/A	
				DWS Full Width?	N/A	
				DWS Offset (in)	N/A	
				Gutter Slope (%)	N/A	
				Gutter X Slope (%)	N/A	
				Painted X Walk2?	No	
				X Walk 2 Direction	To S	
				X Walk 2 Width (in)	N/A	
				X Walk 2 Slope (%)	1.6	
				X Walk 2 X Slope (%)	2.1	
				Ramp inside XWalk2?	N/A	
				Clear Space?	N/A	
				Clear Space to XWalk (in)	N/A	
<p>Total Cost:</p> <p>\$ 3200.00</p>				Storm Grate/Utility Hazard?	N/A	
				Storm Grate/Utility Type		
					N/A	N/A
				Surface Condition? (G/P)	Good	

