## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4080 Main St		reet: DAVID_COX_RD	Cross	Cross Street: REDBRIDGE_TL				Location:	SE
ADA ID: 1413933187D8 Ramp Ty		ype: PerpDiag	Initial F	Initial Pass/Fail: Fail Overall Compliance: N			ce: No	o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	DZVID_ GOX _ DD	Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ramp \	Nith	N/A	Ramp Length (in)	68.0	No	Ramp Slope (%)	10.1
AT .		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	46.0	Yes	Ramp XSlope (%)	0.1
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
<u>6.</u>				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
6. 🔒 🛃		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Party Planter P		Not Found, R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
And a second sec					X Walk 1 Direction	To N		X Walk 2 Direction	To W
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	DAVID COX RD	_			X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	5.1
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	2.7
Street 2 Name	REDBRIDGE TL			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	0.7	N/A	Clear Space?	N/A
	, <b>-</b>				Road X Slope (%)	6.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

