

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 42963 Main Street: RED_ROBIN_ST Cross Street: PRAIRIEGROUSE_CT Location: E

ADA ID: 143A0C5C4E3E Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 46.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 PRAIRIEGROUSE CT StopSign RED ROBIN ST None Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2,
R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance						
Compliance Description		Data	Comp	liance Des	cription	Data
N/A	Ramp Length (in)	46.0	No	Ramp Slop	pe (%)	8.4
No	Ramp Width (in)	46.0	No	Ramp XSI	ope (%)	15.0
N/A	Flare Type LT	N/A	N/A	Flare Type	RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slop	e RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Trav	ersable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Prov	rided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Con	trast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Leng	gth (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full	Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offs	et (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slo	pe (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X S	lope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X	Walk2?	No
	X Walk 1 Direction	To NW		X Walk 2 [Direction	To SW
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 \	Width (in)	N/A
	X Walk 1 Slope (%)	8.4		X Walk 2 S	Slope (%)	2.2
	X Walk 1 X Slope (%)	1.9		X Walk 2	K Slope (%)	10.4
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp insi	de XWalk2?	N/A
	Road Slope (%)	10.9	N/A	Clear Spa	ce?	N/A
	Road X Slope (%)	3.5	N/A	Clear Spa	ce to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Gra	te/Utility Hazard?	N/A

N/A

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Good







Obstruction Type