

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 13408	Main Street: COMMONWEALTH_AV	Cross Street: THE_PLAZA	Location:	N
ADA ID: 1469F44C7DA7	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 2.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	80.0	Yes	Grade Break?	Yes
			Yes	Ramp Width (in)	58.0	No	Grade Break Slope (%)	7.4
			Yes	Ramp Slope (%)	6.7	Yes	Grade Break XSlope (%)	1.5
			Yes	Ramp XSlope (%)	0.2			
			Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
			Yes	Landing Length (in)	64.0	Yes	DWS Provided?	Yes
			Yes	Landing Width (in)	72.5	Yes	DWS Contrast?	Yes
Surveyor Notes:		Yes	Landing Slope (%)	2.0	Yes	DWS Length (in)	24.0	
N/A		Yes	Landing X Slope (%)	0.4	No	DWS Full Width?	No	
PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	No	DWS Offset LT (in)	5.0	
Not Found, R304.5.3, R305.1.4, R305.2, R302.7		N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	5.0	
		No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	2.8	
		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.5	
		N/A	Painted X Walk1?	Yes		Road Slope (%)	1.3	
			X Walk 1 Direction	To SW		Road X Slope (%)	0.3	
			X Walk 1 Width (in)	125.0		Clear Space?	Yes	
			X Walk 1 Slope (%)	1.3	N/A	Clear Space to XWalk (in)	N/A	
			X Walk 1 X Slope (%)	0.3	Yes	Storm Grate/Utility Hazard?	No	
		Yes	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type		
		Yes	Any Obstructions?	No			N/A	
			Obstruction Type		Yes	Surface Condition? (G/P)	Good	
					N/A	Curb Slope (%)	23.2	
Total Cost:		\$ 1600.00						

