## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29218	Main Str	eet: ANASTASIA_CT	Cross Street: KORNIV_DR					Location: E	
ADA ID: 149BB2A01B11		Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliar			nce: No Severity Score: 37.5		37.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
at an and the second	S 1 8	Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp W	/ith	N/A	Ramp Length (in)	48.5	No	Ramp Slope (%)	10.4
		Two New Directional Ramps or	-	Yes	Ramp Width (in)	56.0	No	Ramp XSlope (%)	10.3
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
E.				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		r		N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		1004.2.2, 1004.0.0		N/A	Painted X Walk1?		N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
VY JIN	1 AM			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ANASTASIA CT			10/4	X Walk 1 Slope (%)	6.9		X Walk 2 Slope (%)	4.3
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	4.3 8.7
Street 2 Name	KORNIV DR			N/A	Ramp inside XWalk1?	5.0 N/A	N/A	Ramp inside XWalk2?	0.7 N/A
Stop Condition-Street 1	StopSign			N/A	Road Slope (%)	9.2		Clear Space?	N/A N/A
Stop Condition-Street 1	StopSign								
				<b>NI/A</b>	Road X Slope (%)			Clear Space to XWalk (in)	N/A
		<b>T</b> ( ) <b>O</b> (		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good





