

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9074	Main Street: FORSYTHIA_CR			Cross	Street:	FREEDOM_DR	Location:	NW		
ADA ID: 14AAFD72E681	Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data Compliance Description			
The second se	ALL DA	Remove & Replace Ent	ire Ram	р.	N/A	Ramp Length (in)	83.0	No	Ramp Slope (%)	8.4
	The seal	-		•	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.2
	- Marine Marine				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	and the second second	d.			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		2			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1.1				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second se	1.19	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
6					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
REFE		6			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
DR	1.1				N/A	Shared Landing?	N/A			
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
At Manage	and the second s	Not Found, R304.2.2, R	304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and the second and and		, , , , , , ,			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
A CALL AND A CALL						X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
the second second second second	and and	1			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name FOI	RSYTHIA CR					X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	4.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

