

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44850	Main St	reet: STEELE_CREEK_RD	Cross	Cross Street: SHOPTON RD WEST				Location:	NW
ADA ID: 14FD73E143AB Ramp Type: Perp			initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
	1 23 X	Remove & Replace Entire Ran	ıp.	N/A	Ramp Length (in)	72.0	Yes	Ramp Slope (%)	8.3
	1			No	Ramp Width (in)	38.0	Yes	Ramp XSlope (%)	1.2
	-12 21 200			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	+ to the			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	annier .			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
C C C				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Cinc 1	E .	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the state of the s		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
THE	E.	4		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
GIOPTONLE				N/A	Shared Landing?	N/A			
di la	TIL	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
the second se	118	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	ITE			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
A REAL PROPERTY OF	1 1				X Walk 1 Direction	To S		X Walk 2 Direction	N/A
	1		N/A	X Walk 1 Width (in)	112.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name SHOPTC	ON RD WEST				X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

