

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

Intersection ID: 29469 Main Street: BROOKCHASE LN **Cross Street: DOWNING ST** Location: W **Overall Compliance: No Severity Score:** 25 ADA ID: 15DC420F6A71 Ramp Type: PerpDiag Initial Pass/Fail: Fail

**Codes/Mitigation Info/Possible Solution** 

None

StopSign

## Field Measurements/Component Compliance

Compliance Description

Data



**DOWNING ST** Street 1 Name Stop Condition-Street 2 **BROOKCHASE LN** Street 2 Name Stop Condition-Street 1

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: R304.5.3

N/A 3200.00

N/A

Yes

X Walk 1 Slope (%) Road Slope (%) Road X Slope (%) Any Obstructions? **Obstruction Type** 

Compliance Description

Yes Ramp Slope (%) Ramp Length (in) 53.5 7.7 No Ramp XSlope (%) Ramp Width (in) 48.0 7.7 Flare Type LT N/A N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A **DWS Provided?** N/A Landing Length (in) Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To NE X Walk 2 Direction To SE N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A 0.8 X Walk 2 Slope (%) 3.5 X Walk 2 X Slope (%) X Walk 1 X Slope (%) 6.8 3.2 N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? 3.1 N/A Clear Space? N/A N/A 6.8 Clear Space to XWalk (in) N/A N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





Total Cost:

