


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10041481	Main Street: WESTPARK_DR	Cross Street: N/A	Location: NW
ADA ID: 15E5636D4A19	Ramp Type: PerpDiag	Initial Pass/Fail: Pass	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:	Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Gutter Ponding Observed.	N/A	Ramp Length (in)	60.0	Yes	Ramp Slope (%)	6.9
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.2.3, R305.1.4, R305.2, R302.7</p>		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.0
		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	1.8	No	Flare Slope RT (%)	10.7
		N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
		No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
		No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
		No	Landing Slope (%)	N/A	No	DWS Length (in)	23.0
		No	Landing X Slope (%)	N/A	No	DWS Full Width?	No
		N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	7.0
		N/A	Shared Landing?	N/A			
		No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	2.1
		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	2.0
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
			X Walk 1 Direction	To S		X Walk 2 Direction	To E
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	2.7
			X Walk 1 X Slope (%)	8.6		X Walk 2 X Slope (%)	0.1
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	2.8	N/A	Clear Space?	Yes
			Road X Slope (%)	0.0	N/A	Clear Space to XWalk (in)	N/A
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
			Obstruction Type			Storm Grate/Utility Type	
					N/A		N/A
					Yes	Surface Condition? (G/P)	Good

Total Cost: \$ 3700.00

