cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 45759	Main Street: LEONINE_CT		Cross	Cross Street: GRANDEUR_RD				Location: S	
ADA ID: 16348C744B6A	Ramp Type: PerpDiag		Initial	Initial Pass/Fail: Fail Overall Compliance			nce: N	o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:				Compliance Description Data Compliance Description					Data
	LEONINE CT		\A/;+b	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	8.4
		Remove & Replace Curb Ramp Two New Directional Ramps or	vvitri	No	Ramp Width (in)	40.0	Yes	Ramp XSlope (%)	0.4
		Equivalent.		N/A	Flare Type LT	41.0 N/A	N/A	Flare Type RT	0.5 N/A
				N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A N/A
					,		N/A	Flare Traversable RT?	
CARA STA				N/A	Flare Traversable LT?	N/A			N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
izer				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	A PLON			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	VA.			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	A WAR				X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
	AN AND	2		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	LEONINE CT				X Walk 1 Slope (%)	5.9		X Walk 2 Slope (%)	4.4
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	3.1
Street 2 Name	GRANDEUR RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	2.5	N/A	Clear Space?	N/A
					Road X Slope (%)	5.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		· · · · · · · · · · · · · · · · · ·				N/A			N/A
							1		

Yes Surface Condition? (G/P)

Good

