

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 24035	5 Main Street: ECHO_FOREST_DR			Cross Street: PINEVILLE-MATTHEWS_RD				Location:	W
ADA ID: 16367362535A	A ID: 16367362535A Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance: No				35
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:							Compliance Description Data		
A REAL PROPERTY OF	The second second	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	128.0	No	Ramp Slope (%)	12.9
	5 - 8 - 3/1/4		ne Ramp.	No	Ramp Width (in)	37.0	No	Ramp XSlope (%)	4.7
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Set Stalls			N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A Ben A VS	Star /	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E State Stat		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
La contra	IN/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
States and the second se	Car Nº KA			N/A	Shared Landing?	N/A	1		
	E E	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Not Found, R304.5.1, R304.2			201 2 2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	1 house the	R304.5.3	304.2.2,	N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
				N/A	X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	96.0	N/A	X Walk 2 Width (in)	N/A N/A
			N/A			N/A			
Street 1 Name	ECHO FOREST DR				X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	3.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 185	0.00	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

s Surface Condition? (G/P)

Good

