

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                             |                         |                        |
|------------------------|-----------------------------|-------------------------|------------------------|
| Intersection ID: 30677 | Main Street: DIXIE_HILLS_DR | Cross Street: MARVIN_RD | Location: W            |
| ADA ID: 163E613C29E9   | Ramp Type: BlendTrans1      | Initial Pass/Fail: Fail | Overall Compliance: No |
|                        |                             |                         | Severity Score: 33.75  |

| Codes/Mitigation Info/Possible Solution                                          |                                                                          |            | Field Measurements/Component Compliance |                       |       |            |                             |       |
|----------------------------------------------------------------------------------|--------------------------------------------------------------------------|------------|-----------------------------------------|-----------------------|-------|------------|-----------------------------|-------|
|  | Possible Solutions:                                                      |            | Compliance                              | Description           | Data  | Compliance | Description                 | Data  |
|                                                                                  | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. |            | N/A                                     | Ramp Length (in)      | 46.0  | Yes        | BlendTrans Slope (%)        | 3.0   |
|                                                                                  |                                                                          |            | No                                      | Ramp Width (in)       | 38.0  | No         | BlendTrans XSlope (%)       | 11.6  |
|                                                                                  |                                                                          |            | N/A                                     | Flare Type LT         | N/A   | N/A        | Flare Type RT               | N/A   |
|                                                                                  |                                                                          |            | N/A                                     | Flare Slope LT (%)    | N/A   | N/A        | Flare Slope RT (%)          | N/A   |
|                                                                                  |                                                                          |            | N/A                                     | Flare Traversable LT? | N/A   | N/A        | Flare Traversable RT?       | N/A   |
|                                                                                  |                                                                          |            | N/A                                     | Landing Length (in)   | N/A   | N/A        | DWS Provided?               | N/A   |
|                                                                                  |                                                                          |            | N/A                                     | Landing Width (in)    | N/A   | N/A        | DWS Contrast?               | N/A   |
|                                                                                  |                                                                          |            | N/A                                     | Landing Slope (%)     | N/A   | N/A        | DWS Length (in)             | N/A   |
|                                                                                  |                                                                          |            | N/A                                     | Landing X Slope (%)   | N/A   | N/A        | DWS Full Width?             | N/A   |
| Surveyor Notes:<br><br>N/A                                                       |                                                                          |            | N/A                                     | Landing Curb? (Y/N)   | N/A   | N/A        | DWS Offset (in)             | N/A   |
|                                                                                  |                                                                          |            | N/A                                     | Shared Landing?       | N/A   |            |                             |       |
|                                                                                  |                                                                          |            | N/A                                     | Gutter Ponding?       | N/A   | N/A        | Gutter Slope (%)            | N/A   |
|                                                                                  |                                                                          |            | N/A                                     | Gutter Lip Ht (in)    | N/A   | N/A        | Gutter X Slope (%)          | N/A   |
|                                                                                  |                                                                          |            | N/A                                     | Painted X Walk1?      | No    | N/A        | Painted X Walk2?            | No    |
|                                                                                  |                                                                          |            |                                         | X Walk 1 Direction    | To SE |            | X Walk 2 Direction          | To NE |
|                                                                                  |                                                                          |            |                                         | X Walk 1 Width (in)   | N/A   |            | X Walk 2 Width (in)         | N/A   |
|                                                                                  |                                                                          |            |                                         | X Walk 1 Slope (%)    | 3.0   |            | X Walk 2 Slope (%)          | 3.8   |
|                                                                                  |                                                                          |            |                                         | X Walk 1 X Slope (%)  | 4.3   |            | X Walk 2 X Slope (%)        | 7.2   |
|                                                                                  |                                                                          |            | N/A                                     | Ramp inside XWalk1?   | N/A   | N/A        | Ramp inside XWalk2?         | N/A   |
| PROW/ADA:<br><br>Not Found, R304.5.1, R304.5.3                                   |                                                                          |            |                                         | Road Slope (%)        | 6.7   |            | Clear Space?                | N/A   |
|                                                                                  |                                                                          |            |                                         | Road X Slope (%)      | 1.6   | N/A        | Clear Space to XWalk (in)   | N/A   |
|                                                                                  |                                                                          |            | N/A                                     | Any Obstructions?     | N/A   | N/A        | Storm Grate/Utility Hazard? | N/A   |
|                                                                                  |                                                                          |            |                                         | Obstruction Type      |       |            | Storm Grate/Utility Type    |       |
|                                                                                  |                                                                          |            |                                         |                       | N/A   |            |                             | N/A   |
|                                                                                  |                                                                          |            |                                         |                       |       | Yes        | Surface Condition? (G/P)    | Good  |
|                                                                                  |                                                                          |            |                                         |                       |       | No         | Curb Slope (%)              | 12.7  |
|                                                                                  |                                                                          |            |                                         |                       |       |            |                             |       |
|                                                                                  |                                                                          |            |                                         |                       |       |            |                             |       |
|                                                                                  |                                                                          |            |                                         |                       |       |            |                             |       |
| Total Cost:                                                                      |                                                                          | \$ 3200.00 |                                         |                       |       |            |                             |       |

