

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30450 Main Street: STEELE_CREEK_RD Cross Street: SMOKE_MONT_DR Location: SW ADA ID: 1658F114C56B Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance:: No Severity Score: 25 Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance Severity Score: 25 Codes/Mitigation Info/Possible Solutions: Remove & Replace Entire Ramp. N/A Ramp Length (in) 56.0 No Ramp Slope (%) 12.6 Ves Ramp Width (in) 48.0 Yes Ramp Slope (%) 10 N/A Flare Type LT N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A N/A Location: Surveyor Notes: N/A Location: Surveyor Notes: N/A N/A Location: Surveyor Notes: N/A N/A Location: Surveyor Notes: N/A M/A Location: Surveyor Notes: N/A N/A Location: Surveyor Notes: N/A Location: Surveyor Notes: N/A N/A Location: Surveyor Notes: N/A Location:
Codes/Mitigation Info/Possible Solutions: Field Measurements/Component Compliance Possible Solutions: Possible Solutions: Remove & Replace Entire Ramp. N/A Remove & Replace Entire Ramp. N/A N/A Ramp Length (in) 56.0 Yes Ramp XSlope (%) 1.0 N/A Flare Type LT N/A N/A Flare Slope LT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable LT? N/A N/A Flare Traversable LT? N/A N/A Landing Length (in) N/A DWS Provided? N/A N/A Landing Slope (%) N/A N/A N/A Landing Slope (%) N/A N/A DWS Contrast? N/A N/A Landing Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A DWS Offset (in) N/A
Possible Solutions: Compliance Description Data Compliance Description Data N/A Ramp Length (in) 56.0 No Ramp Slope (%) 12.6 Yes Ramp Width (in) 48.0 Yes Ramp XSlope (%) 1.0 N/A Flare Type LT N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A DWS Provided? N/A N/A Landing Slope (%) N/A DWS Contrast? N/A N/A Landing Slope (%) N/A DWS Contrast? N/A N/A Landing Slope (%) N/A DWS Length (in) N/A N/A Landing Curb? (Y/N) N/A DWS Offset (in) N/A
Remove & Replace Entire Ramp.N/ARamp Length (in)56.0NoRamp Slope (%)12.6YesRamp Width (in)48.0YesRamp XSlope (%)1.0N/AFlare Type LTN/AN/AFlare Type RTN/AN/AFlare Slope LT (%)N/AN/AFlare Slope RT (%)N/AN/AFlare Traversable LT?N/AN/AFlare Traversable RT?N/AN/ALanding Length (in)N/AN/ADWS Provided?N/AN/ALanding Slope (%)N/AN/ADWS Contrast?N/AN/ALanding Slope (%)N/AN/ADWS Contrast?N/AN/ALanding Slope (%)N/AN/ADWS Full Width?N/AN/ALanding Curb? (Y/N)N/AN/ADWS Offset (in)N/A
Yes Ramp Width (in) 48.0 Yes Ramp XSlope (%) 1.0 N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A DWS Provided? N/A N/A Landing Slope (%) N/A DWS Contrast? N/A N/A Landing Slope (%) N/A DWS Length (in) N/A N/A Landing Curb? (Y/N) N/A DWS Offset (in) N/A
YesRamp Width (in)48.0YesRamp XSlope (%)1.0N/AFlare Type LTN/AK/AFlare Type RTN/AN/AFlare Slope LT (%)N/AN/AFlare Slope RT (%)N/AN/AFlare Traversable LT?N/AN/AFlare Traversable RT?N/AN/ALanding Length (in)N/AN/ADWS Provided?N/AN/ALanding Slope (%)N/AN/ADWS Contrast?N/AN/ALanding Slope (%)N/AN/ADWS Length (in)N/AN/ALanding X Slope (%)N/AN/ADWS Full Width?N/AN/ALanding Curb? (Y/N)N/ADWS Offset (in)N/A
N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A DWS Provided? N/A N/A Landing Width (in) N/A DWS Contrast? N/A N/A Landing Slope (%) N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A DWS Offset (in) N/A
N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A Landing Width (in) N/A N/A DWS Contrast? N/A N/A Landing Slope (%) N/A N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A DWS Offset (in) N/A
N/ALanding Length (in)N/AN/ADWS Provided?N/AN/ALanding Width (in)N/AN/ADWS Contrast?N/AN/ALanding Slope (%)N/AN/ADWS Length (in)N/AN/ALanding X Slope (%)N/AN/ADWS Full Width?N/AN/ALanding Curb? (Y/N)N/ADWS Full Width?N/A
Surveyor Notes: N/A Landing Width (in) N/A DWS Contrast? N/A N/A Landing Slope (%) N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A DWS Ontrast? N/A
Surveyor Notes: N/A Landing Width (in) N/A N/A DWS Contrast? N/A N/A Landing Slope (%) N/A N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A DWS Offset (in) N/A N/A Shared Landing? N/A DWS Offset (in) N/A
N/A N/A Landing Slope (%) N/A N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A N/A N/A N/A
N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A N/A N/A N/A
N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A
N/A Shared Landing? N/A
PROW/ADA: N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A
Not Found, R304.2.2 N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A
N/A Painted X Walk1? No N/A Painted X Walk2? N/A
X Walk 1 Direction To SE X Walk 2 Direction N/A
N/A X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A
Street 1 Name STEELE CREEK RD X Walk 1 Slope (%) 4.6 X Walk 2 Slope (%) N/A
Stop Condition-Street 2 None X Walk 1 X Slope (%) 0.8 X Walk 2 X Slope (%) N/A
Street 2 Name N/A N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A
Stop Condition-Street 1 N/A N/A Clear Space? N/A
Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A
N/A Any Obstructions? N/A N/A Storm Grate/Utility Hazard? N/A
Total Cost: \$ 1850.00 Obstruction Type Storm Grate/Utility Type
N/A N/A

Yes Surface Condition? (G/P)

Good

