cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 21800	ntersection ID: 21800 Main Street: MILL_POND_RD Cro					ross Street: SCHOOL_HOUSE_LN			
ADA ID: 16620ADB3EA2							Location: Severity Score:	<u>W</u> 21.25	
			initial P	nitial Pass/Fail: Fail Overall Compliance: No					21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	75.0	No	Ramp Slope (%)	8.9
		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	45.0	Yes	Ramp XSlope (%)	1.0
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	11/200			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	-			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	S (Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A A A	X	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
STATISTICS STATISTICS	11 279			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A STATE OF A				N/A	Shared Landing?	N/A			
	and a l	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A BAR DE	CARDON AN	Not Found, R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	and the	, ,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	A Star Star				X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
TI HAR AFT . Land of				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	SCHOOL HOUSE LN				X Walk 1 Slope (%)	4.5		X Walk 2 Slope (%)	7.0
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	5.3		X Walk 2 X Slope (%)	2.0
Street 2 Name	MILL POND RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	2.4	N/A	Clear Space?	N/A
					Road X Slope (%)	7.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

