

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 10952	Main Str	Main Street: N_GRAHAM_ST			Cross Street: STATESVILLE_AV			Location: N	
ADA ID: 1664674B471E									
· · · ·								21.25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	A L	Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Entire	e Ramp.	N/A	Ramp Length (in)	59.0	No	Ramp Slope (%)	11.7
e de la companya de				No	Ramp Width (in)	46.5	Yes	Ramp XSlope (%)	1.9
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	6 8			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	SI IN	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	Se la	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	5			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
G. S. S.				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A				
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1, R3	04.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
X X			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
<u>6</u>					X Walk 1 Direction	To W		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	124.5	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	STATESVILLE AV				X Walk 1 Slope (%)	4.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 18	50.00	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

